


EXHIBIT 19

| | | | | |
|---|------------------------------|-----------------|-------------|---------------|
|  | INSPECTION REPORT | Report Date: | 11 DECEMBER | Conclusion |
| | | Inspection No.: | CT41939 | Passed |
| | | Revise No.: | CTS-HN02-R3 | Page 1 of 25 |


| | | | |
|----------------------|---|--|--|
| Client: | Kitchen Winners INC | | |
| Supplier Name: | Qingdao Yuantong Bomei Agricultural products International Logistics Development Co., LTD | | |
| Factory Name: | Zhonghong Pulin Medical Products Co.,Ltd | | |
| Inspection Service: | Final Random Inspection |  | |
| P/O Number: | 20248/20249 | | |
| Style Number: | -- | | |
| P/O Quantity: | 150,400,000Pieces | | |
| Color: | Blue | | |
| Destination Country: | -- | | |
| Inspection date: | Dec 11 th , 2020 | | |
| Product Description: | Nitrile examination gloves | | |
| Place of Inspection: | Tianchang, Anhui, China | | |

The inspection results of the above mentioned merchandise were found as follows:

| | Description | Passed | Failed | Pending | N.A. | Remark |
|---|-------------------------|--------|--------|---------|------|--------|
| 1 | Quantity Available | X | | | | |
| 2 | Workmanship for product | X | | | | |
| 3 | On-site tests | X | | | | |
| 4 | Specification | X | | | | |
| 5 | Packing | X | | | | |
| 6 | Marking & Labeling | X | | | | |
| 7 | Data Check | X | | | | |

| | | | |
|--------------------------------|-----------------------|------------------------------|----------|
| OVERALL CONCLUSION: | PASSED | | |
| Inspector(s) Arrived Time: | 9:00 AM | Inspector(s) Departure Time: | 18:30 PM |
| Inspector(s) Name: | Rex Chen & Robin Wang | | |
| Report reviewer: | Lucas Yang | | |

| | |
|-------|--|
| Note: | |
| 1 | The G.W. and N.W on master carton was not marked on master carton. |

| | | | | |
|---|--------------------------|-----------------|-------------|---------------|
|  | INSPECTION REPORT | Report Date: | 11 DECEMBER | Conclusion |
| | | Inspection No.: | CT41939 | Passed |
| | | Revise No.: | CTS-HN02-R3 | Page 2 of 25 |

INSPECTION RESULTS:

The inspection results were found as follows:

1) : QUANTITY AVAILABLE:

A: Quantity details

| Quantity | | | | Unit: Pieces | | | | |
|----------|------|-----------|---------|--------------|----------|--------------------|-----------|----------|
| P.O No. | Size | Order Qty | CTN Qty | Sample size | | Quantity Breakdown | | |
| | | | | Packed | Unpacked | Unfinished | Packed | Unpacked |
| 20248 | S | 10000000 | 1000 | 83 | 0 | 0 | 10000000 | 0 |
| | M | 40000000 | 4000 | 33 | 0 | 0 | 40000000 | 0 |
| | L | 40000000 | 4000 | 332 | 0 | 0 | 40000000 | 0 |
| | XL | 10000000 | 1000 | 83 | 0 | 0 | 10000000 | 0 |
| 20249 | S | 8640000 | 864 | 72 | 0 | 0 | 8640000 | 0 |
| | M | 34560000 | 3456 | 288 | 0 | 0 | 34560000 | 0 |
| | L | 34560000 | 3456 | 287 | 0 | 0 | 34560000 | 0 |
| | XL | 8640000 | 864 | 72 | 0 | 0 | 8640000 | 0 |
| Total | | 150400000 | 18640 | 1250 | 0 | 0 | 150400000 | 0 |

B: Random selected carton number

| P.O No. | Size | Ctn Qty | CTN NO. | | | | | | | | | |
|---------|--|---------|---------|----|--|--|--|--|--|--|--|--|
| 20248 | S | 7 | -- | -- | | | | | | | | |
| | M | 29 | -- | -- | | | | | | | | |
| | L | 29 | -- | -- | | | | | | | | |
| | XL | 7 | -- | -- | | | | | | | | |
| 20249 | S | 7 | -- | -- | | | | | | | | |
| | M | 25 | -- | -- | | | | | | | | |
| | L | 26 | -- | -- | | | | | | | | |
| | XL | 7 | -- | -- | | | | | | | | |
| Note: | No Carton number carton marked on master carton. | | | | | | | | | | | |


2) WORKMANSHIP for PRODUCT:





| Inspection Standard: ANSI/ASQ Z1.4 | | | | Defects | | |
|---|-------------|---------------|--|----------|-------|-------|
| | | | | Critical | Major | Minor |
| Sampling Plan: | General | AQL: | | 0 | 2.5 | 4.0 |
| Inspection Level: | Level II | Actual Found: | | 0 | 9 | 9 |
| Sample Size: | 1250 Pieces | Max.Allow: | | 0 | 21 | 21 |
| Workmanship Defects/Function Inspection Finding | | | | | | |
| P.O No. | Description | | | Cr | Ma | Mi |


CTS-INSPECTION SERVICES CO., LTD

Tel: +86 571 8865 2781 Fax: +86 571 8863 2737 E-mail: CTS@CTS-Inspection.com

CTS-Inspection Copyright © All Rights Reserved

| | | | | |
|---|------------------------------|-----------------|-------------|---------------|
|  | INSPECTION REPORT | Report Date: | 11 DECEMBER | Conclusion |
| | | Inspection No.: | CT41939 | Passed |
| | | Revise No.: | CTS-HN02-R3 | Page 3 of 25 |

| | | | | |
|---|---|--|---|---|
| 20248/249 | Uneven nitrile(harder than other part of glove) | 0 | 6 | 0 |
| | Glue mark at gift box | 0 | 0 | 2 |
| | Damaged gift box | 0 | 0 | 2 |
| | Stain marks | 0 | 0 | 1 |
| | | | | |
| Total defect found: | | 0 | 6 | 5 |
| Deefct - Uneven nitrile(harder than other part of glove) – Ma | | Deefct - Uneven nitrile(harder than other part of glove) – Ma | | |
|  | |  | | |
| Deefct - Uneven nitrile(harder than other part of glove) – Ma | | Deefct - Uneven nitrile(harder than other part of glove) – Ma | | |
|  | |  | | |
| Deefct - Uneven nitrile(harder than other part of glove) – Ma | | Deefct - Uneven nitrile(harder than other part of glove) – Ma | | |


| | | | | |
|---|------------------------------|-----------------|-------------|---------------|
|  | INSPECTION REPORT | Report Date: | 11 DECEMBER | Conclusion |
| | | Inspection No.: | CT41939 | Passed |
| | | Revise No.: | CTS-HN02-R3 | Page 4 of 25 |




Deefct - Damaged gift box – Mi



Deefct - Damaged gift box – Mi




Deefct - Glue mark at gift box – Mi



Deefct - Stain marks – Mi



| | | | | |
|---|------------------------------|-----------------|-------------|---------------|
|  | INSPECTION REPORT | Report Date: | 11 DECEMBER | Conclusion |
| | | Inspection No.: | CT41939 | Passed |
| | | Revise No.: | CTS-HN02-R3 | Page 5 of 25 |

3) On-site Tests:


| No. | Description | Sample size | Result |
|-----|--|-------------|--------|
| 1 | Transportation drop check on master carton | 1 carton | Passed |
| 2 | Size measurement | 13 pieces | Passed |
| 3 | Function & Performance check | 13 pieces | Passed |
| 4 | Fitting check | 32 pieces | Passed |
| 5 | Pulling test | 13 pieces | Passed |
| 6 | Smell test | 13 pieces | Passed |
| 7 | The Window of gift box using function test | 5 pieces | Passed |
| 8 | The water leaking test | 13 pieces | Passed |

4) SPECIFICATION

| Description | Findings |
|--|--------------------|
| Check against order | |
| The inspected samples were found similar to the description of order | -- |
| Discrepancy was found. Please refer to Special Attention on last page | -- |
| Check against sample | -- |
| The inspected samples were found similar to conformity sample submitted by Factory | Passed |
| No conformity sample was provided by client or supplier for style & color comparison | -- |
| Discrepancy was found. Please refer to Special Attention on last page | -- |
| <u>Description</u> | <u>Provided By</u> |
| The inspected samples were consistent with | |
| - Purchase Order | -- |
| - Performa Invoice | Client |
| - Specification | -- |
| - Submitted sample | -- |
| - Digital photo | -- |
| Instruction manual and documentation check | -- |
| - The components of inspected samples were compared with the provided CDF. | -- |

5) PACKAGING:

| | | | |
|-------------------------|---|-------------|-----|
| Export Carton Details | | | |
| Fastening Metal Staples | X | New or Used | New |
| Material | Cardboard | Seal band | X |
| Nailing or Not | X | X | X |
| Packing method | | | |
| 1 | One Hundred(100) pieces packed into a gift box. | | |

| | | | | |
|---|------------------------------|-----------------|-------------|---------------|
|  | INSPECTION REPORT | Report Date: | 11 DECEMBER | Conclusion |
| | | Inspection No.: | CT41939 | Passed |
| | | Revise No.: | CTS-HN02-R3 | Page 6 of 25 |

| | |
|---|--|
| 2 | Ten(10) piece gift boxes packed into a double-wall corrugated master carton sealed with gummed tape. |
| 1 | One Thousand (1000) pieces packed into a double-wall corrugated master carton sealed with gummed tape. |

6) MARKING & LABELING:

| Barcode/Labelling/Printing | | |
|--|-------------------------|--------|
| Description | Location | Result |
| Barcode | -- | -- |
| Label | -- | -- |
| Logo | Master carton/Color box | Passed |
| Content of instruction | Master carton/Color box | Passed |
| Printing | Master carton/Color box | Passed |
| Shippint Marks | | |
| Shipping Marks (on <u>2</u> side(s)) | | Passed |
| Side Marks (on <u>2</u> side(s)) | | Passed |
| Inner Box Marks (on <u> </u> side(s)) | | -- |
| Colour Box Marks (on <u>6</u> side(s)) | | Passed |

7) DATE CHECK

A: Carton check


| PO No. | Size | Carton size(cm) | Carton weight(kg) | Bar code view | Bar code scanning |
|-----------|------|-----------------|-------------------|---------------|-------------------|
| 20248/249 | S | 34*24.5*27 | 5.25 | -- | -- |
| | M | | 6.4 | -- | -- |
| | L | | 6.05 | -- | -- |
| | XL | | 6.65 | -- | -- |

B: Gift Box check

| PO No. | Size | Box size(cm) | Box weight(g) | Bar code view | Bar code scanning |
|-----------|------|--------------|---------------|---------------|-------------------|
| 20248/249 | S | 23*12.5*6.5 | 508.6 | -- | -- |
| | M | | 609.7 | -- | -- |
| | L | | 602.6 | -- | -- |
| | XL | | 633.9 | -- | -- |

C: Product check


| PO No. | Size | Product size(cm) | Product weight(g) | Bar code view | Bar code scanning |
|-----------|------|------------------|-------------------|---------------|-------------------|
| 20248/249 | S | 24*8.5 | 48/52 | -- | -- |
| | M | 24*10.0 | 58/58 | -- | -- |
| | L | 24*10.5 | 59/58 | -- | -- |
| | XL | 24*11 | 67/68 | -- | -- |

| | | | | |
|---|------------------------------|-----------------|-------------|---------------|
|  | INSPECTION REPORT | Report Date: | 11 DECEMBER | Conclusion |
| | | Inspection No.: | CT41939 | Passed |
| | | Revise No.: | CTS-HN02-R3 | Page 7 of 25 |

入库明细

| 入库时间 (date) | 入库数量quantity | S | M | L | XL |
|-------------|--------------|-------|-------|-------|-------|
| 8-Dec | 100000 | 10000 | 40000 | 40000 | 10000 |
| 8-Dec | 86400 | 8640 | 34560 | 34560 | 8640 |
| 8-Dec | 25000 | 2500 | 10000 | 10000 | 2500 |
| | 211400 | | | | |

2020/12/11

| | | | | |
|---|------------------------------|-----------------|-------------|---------------|
|  | INSPECTION REPORT | Report Date: | 11 DECEMBER | Conclusion |
| | | Inspection No.: | CT41939 | Passed |
| | | Revise No.: | CTS-HN02-R3 | Page 8 of 25 |


POTOS ATTACHMENT

| | |
|--|---|
| Carton view | Shipping mark on 2 wider sides view |
|  |  |
| Shipping mark on 1 wider side view | Top side view |
|  |  |
| Shipping mark on 1 wider side view for S | Shipping mark on 1 wider side view for M |

CTS-INSPECTION SERVICES CO., LTD

Tel: +86 571 8865 2781 Fax: +86 571 8863 2737 E-mail: CTS@CTS-Inspection.com

CTS-Inspection Copyright © All Rights Reserved

| | | | | |
|---|------------------------------|-----------------|-------------|---------------|
|  | INSPECTION REPORT | Report Date: | 11 DECEMBER | Conclusion |
| | | Inspection No.: | CT41939 | Passed |
| | | Revise No.: | CTS-HN02-R3 | Page 9 of 25 |



Shipping mark on1 wider side view for L



Shipping mark on1 wider side view for XL



Open carton



3PLY



Gift box view




Gift box view

CTS-INSPECTION SERVICES CO., LTD

Tel: +86 571 8865 2781 Fax: +86 571 8863 2737 E-mail: CTS@CTS-Inspection.com

CTS-Inspection Copyright © All Rights Reserved

| | | | | |
|---|------------------------------|-----------------|-------------|---------------|
|  | INSPECTION REPORT | Report Date: | 11 DECEMBER | Conclusion |
| | | Inspection No.: | CT41939 | Passed |
| | | Revise No.: | CTS-HN02-R3 | Page 10 of 25 |



Gift box view



Gift box view



Gift box view



Gift box view



Gift box view




Gift box view

CTS-INSPECTION SERVICES CO., LTD

Tel: +86 571 8865 2781 Fax: +86 571 8863 2737 E-mail: CTS@CTS-Inspection.com

CTS-Inspection Copyright © All Rights Reserved

| | | | | |
|---|------------------------------|-----------------|-------------|---------------|
|  | INSPECTION REPORT | Report Date: | 11 DECEMBER | Conclusion |
| | | Inspection No.: | CT41939 | Passed |
| | | Revise No.: | CTS-HN02-R3 | Page 11 of 25 |



Gift box view for S



Gift box view for M



Gift box view for L



Gift box view for XL



Open gift box




Unit packing

CTS-INSPECTION SERVICES CO., LTD

Tel: +86 571 8865 2781 Fax: +86 571 8863 2737 E-mail: CTS@CTS-Inspection.com

CTS-Inspection Copyright © All Rights Reserved

| | | | | |
|---|------------------------------|-----------------|-------------|---------------|
|  | INSPECTION REPORT | Report Date: | 11 DECEMBER | Conclusion |
| | | Inspection No.: | CT41939 | Passed |
| | | Revise No.: | CTS-HN02-R3 | Page 12 of 25 |



Certificate



Product view



Submitted sample(L) and production sample(R) for S




Submitted sample(L) and production sample(R) for S



Submitted sample(L) and production sample(R) for M



Submitted sample(L) and production sample(R) for M

| | | | | |
|---|------------------------------|-----------------|-------------|---------------|
|  | INSPECTION REPORT | Report Date: | 11 DECEMBER | Conclusion |
| | | Inspection No.: | CT41939 | Passed |
| | | Revise No.: | CTS-HN02-R3 | Page 13 of 25 |



Submitted sample(L) and production sample(R) for L



Submitted sample(L) and production sample(R) for L



Submitted sample(L) and production sample(R) for XL




Submitted sample(L) and production sample(R) for XL



Master carton size check for length - 34cm



Master carton size check for length - 34cm

| | | | | |
|---|------------------------------|-----------------|-------------|---------------|
|  | INSPECTION REPORT | Report Date: | 11 DECEMBER | Conclusion |
| | | Inspection No.: | CT41939 | Passed |
| | | Revise No.: | CTS-HN02-R3 | Page 14 of 25 |



Master carton size check for width - 24.5cm



Master carton size check for width - 24.5cm



Master carton size check for height - 27cm



Master carton size check for height - 27cm



Gift box size - 23cm




Gift box size - 23cm

CTS-INSPECTION SERVICES CO., LTD

Tel: +86 571 8865 2781 Fax: +86 571 8863 2737 E-mail: CTS@CTS-Inspection.com

CTS-Inspection Copyright © All Rights Reserved


| | | | | |
|---|------------------------------|-----------------|-------------|---------------|
|  | INSPECTION REPORT | Report Date: | 11 DECEMBER | Conclusion |
| | | Inspection No.: | CT41939 | Passed |
| | | Revise No.: | CTS-HN02-R3 | Page 15 of 25 |




Gift box size - 12.5cm



Gift box size - 6.5cm



Product length for S - 24cm




Product width for S - 9cm



Product length for M - 24cm



Product width for M - 10cm

| | | | | |
|---|------------------------------|-----------------|-------------|---------------|
|  | INSPECTION REPORT | Report Date: | 11 DECEMBER | Conclusion |
| | | Inspection No.: | CT41939 | Passed |
| | | Revise No.: | CTS-HN02-R3 | Page 16 of 25 |



Product length for L - 24cm



Product width for L - 10.5



Product length for XL - 24cm




Product width for XL - 11cm



Thickness check



Thickness check

| | | | | |
|---|------------------------------|-----------------|-------------|---------------|
|  | INSPECTION REPORT | Report Date: | 11 DECEMBER | Conclusion |
| | | Inspection No.: | CT41939 | Passed |
| | | Revise No.: | CTS-HN02-R3 | Page 17 of 25 |



Thickness check



Thickness check



Thickness check




Thickness check



Thickness check



Thickness check

| | | | | |
|---|------------------------------|-----------------|-------------|---------------|
|  | INSPECTION REPORT | Report Date: | 11 DECEMBER | Conclusion |
| | | Inspection No.: | CT41939 | Passed |
| | | Revise No.: | CTS-HN02-R3 | Page 18 of 25 |



Weight of master carton for S



Weight of master carton for M



Weight of master carton for L



Weight of master carton for XL



Gift box weight for S




Gift box weight for M

CTS-INSPECTION SERVICES CO., LTD

Tel: +86 571 8865 2781 Fax: +86 571 8863 2737 E-mail: CTS@CTS-Inspection.com

CTS-Inspection Copyright © All Rights Reserved

| | | | | |
|---|--------------------------|-----------------|-------------|---------------|
|  | INSPECTION REPORT | Report Date: | 11 DECEMBER | Conclusion |
| | | Inspection No.: | CT41939 | Passed |
| | | Revise No.: | CTS-HN02-R3 | Page 19 of 25 |



Gift box weight for L



Gift box weight for XL



Product weight check for S




Product weight check for S



Product weight check for M



Product weight check for M

| | | | | |
|---|------------------------------|-----------------|-------------|---------------|
|  | INSPECTION REPORT | Report Date: | 11 DECEMBER | Conclusion |
| | | Inspection No.: | CT41939 | Passed |
| | | Revise No.: | CTS-HN02-R3 | Page 20 of 25 |



Product weight check for L



Product weight check for XL



Product weight for XL




Product weight for XL



Carton drop test



Carton drop test

| | | | | |
|---|------------------------------|-----------------|-------------|---------------|
|  | INSPECTION REPORT | Report Date: | 11 DECEMBER | Conclusion |
| | | Inspection No.: | CT41939 | Passed |
| | | Revise No.: | CTS-HN02-R3 | Page 21 of 25 |



Smell test



Fitting test



Fitting test




Fitting test



Pulling test



Pulling test

| | | | | |
|---|------------------------------|-----------------|-------------|---------------|
|  | INSPECTION REPORT | Report Date: | 11 DECEMBER | Conclusion |
| | | Inspection No.: | CT41939 | Passed |
| | | Revise No.: | CTS-HN02-R3 | Page 22 of 25 |



Pulling test



Pulling test



Pulling test




Pulling test



Pulling test



Pulling test

| | | | | |
|---|------------------------------|-----------------|-------------|---------------|
|  | INSPECTION REPORT | Report Date: | 11 DECEMBER | Conclusion |
| | | Inspection No.: | CT41939 | Passed |
| | | Revise No.: | CTS-HN02-R3 | Page 23 of 25 |



Pulling test



Pulling test



Pulling test




Pulling test



Water leaking test



Open check

| | | | | |
|---|------------------------------|-----------------|-------------|---------------|
|  | INSPECTION REPORT | Report Date: | 11 DECEMBER | Conclusion |
| | | Inspection No.: | CT41939 | Passed |
| | | Revise No.: | CTS-HN02-R3 | Page 24 of 25 |




Open check




Open check



Open check



Goods in warehouse



Goods in warehouse




Goods in warehouse

CTS-INSPECTION SERVICES CO., LTD

Tel: +86 571 8865 2781 Fax: +86 571 8863 2737 E-mail: CTS@CTS-Inspection.com

CTS-Inspection Copyright © All Rights Reserved

| | | | | |
|---|------------------------------|-----------------|-------------|---------------|
|  | INSPECTION REPORT | Report Date: | 11 DECEMBER | Conclusion |
| | | Inspection No.: | CT41939 | Passed |
| | | Revise No.: | CTS-HN02-R3 | Page 25 of 25 |



Goods in warehouse



N/A



N/A